

FIELD REPORT

DATE: July 25, 2013

PROJECT: Independence Park Main Library

WEATHER CONDITIONS: Scattered Clouds - 83°

SITE CONDITIONS: Dry WORKERS: -

REPORTED BY: Benjamin R. Bradford, The Library Design Collaborative

IN ATTENDANCE: Benjamin R. Bradford

OBSERVATIONS:

1) The Monthly Owner's Meeting has held today.

- 2) The flood tests on both green roofs have been completed.
- 3) The temporary cut-in (permanent power) has been connected.
- 4) The metal column covers are being installed.
- 5) The millwork installation has begun.
- 6) The following work is being installed:
 - a. Zinc wall panels
 - b. Curtainwall
 - c. Masonry
 - d. Metal studs
 - e. Interior gypsum board
 - f. Millwork

CONSTRUCTION SCHEDULE:

 The A/C should be turned on in couple weeks after the permanent power is connected.

ATTACHMENTS:

1) Two (2) pages of photographs from the site visit.

This report is not an exact record of discussions held, but a general understanding of topics discussed from the notes taken by the author. If there is an error, omission, or correction required, please contact the Architect in writing within three days of receipt of this report.















