

FIELD REPORT

DATE: May 23, 2013
PROJECT: Independence Park Main Library
WEATHER CONDITIONS: Partly Cloudy - 77°
SITE CONDITIONS: Wet
WORKERS: +/- 115
REPORTED BY: Benjamin R. Bradford, The Library Design Collaborative

IN ATTENDANCE: Benjamin R. Bradford

OBSERVATIONS:

- 1) The loading dock grade beam has been poured.
- 2) The water lines appear to be installed to the water company connection point at Goodwood Boulevard.
- 3) The gypsum board is being installed in the two-story reading room.
- 4) On the first floor, gypsum board furr downs are installed.
- 5) The following work is being installed:
 - a. Masonry
 - b. Zinc wall panels
 - c. Curtainwall
 - d. Exterior gypsum board sheathing
 - e. Metal studs
 - f. Air barrier
 - g. Sprinkler system piping
 - h. Interior gypsum board.

CONSTRUCTION SCHEDULE:

- 1) The Loading dock concrete pour should occur in the upcoming weeks.

ATTACHMENTS:

- 1) Two (2) pages of photographs from the site visit.



