

FIELD REPORT

DATE: July 18, 2013

PROJECT: Independence Park Main Library

**WEATHER CONDITIONS:** Partly Cloudy - 85° SITE CONDITIONS: Slightly Muddy

WORKERS: -

**REPORTED BY:** Benjamin R. Bradford, The Library Design Collaborative

**IN ATTENDANCE**: Benjamin R. Bradford

## **OBSERVATIONS:**

- 1) The flood test has started on the south green roof.
- 2) The cistern has been installed on the third floor roof.
- 3) The acoustical plaster panels are being installed.
- 4) An air conditioner has been installed to condition the two story space for the installation of the acoustical plaster.
- 5) The steel for the art wall has been installed.
- 6) The ceramic tile in the family restrooms has been installed.
- 7) The masonry installation at the Meeting Room continues.
- 8) The following work is being installed:
  - a. Zinc wall panels
  - b. Curtainwall
  - c. Exterior gypsum board sheathing
  - d. Masonry
  - e. Metal studs
  - f. Interior gypsum board.

## CONSTRUCTION SCHEDULE:

- 1) The permanent power should be connected soon.
- 2) The A/C should be turned on in couple weeks after the permanent power is connected.
- 3) The flood tests for the north green roof should occur at the end of this week.

## ATTACHMENTS:

1) Two (2) pages of photographs from the site visit.

This report is not an exact record of discussions held, but a general understanding of topics discussed from the notes taken by the author. If there is an error, omission, or correction required, please contact the Architect in writing within three days of receipt of this report.















