

FIELD REPORT

DATE: November 21, 2012

PROJECT: Independence Park Main Library

WEATHER CONDITIONS: Clear - 70°

SITE CONDITIONS: Dry WORKERS: +/- 55

REPORTED BY: Benjamin R. Bradford, The Library Design Collaborative

IN ATTENDANCE: Benjamin R. Bradford & Robbie Posey

OBSERVATIONS:

1) The third floor curtainwall curb has been poured.

- 2) The Contractor was notified to hold on the following work items. The Contractor shall notify the Architect 4 days prior to any delays in construction and any work related to this area will the at the Contractor's own risk.
 - All work related to the wall construction between MEN'S (109) and CORRIDOR (106) until resolution to the plumbing vent location has been submitted.
 - b. All work related to the butterfly roof soffit framing.
 - c. All work associated or around FIRE PUMP (163)
- 3) The following work is being installed:
 - a. Exterior gypsum board sheathing
 - b. Metal studs
 - c. Fireproofing
 - d. Plumbing piping
 - e. Mechanical duct
 - f. Sprinkler system piping
 - q. Electrical conduits and junction boxes

CONSTRUCTION SCHEDULE:

- 1) The concrete pour for the third floor roof cistern is expected to occur next week.
- 2) Zinc wall panel installation is expected to start within the month.
- 3) Brick installation is expected to start within the month.
- 4) Curtainwall installation is expected to start in the next couple of weeks.

ATTACHMENTS:

1) Two (2) pages of photographs from the site visit.

This report is not an exact record of discussions held, but a general understanding of topics discussed from the notes taken by the author. If there is an error, omission, or correction required, please contact the Architect in writing within three days of receipt of this report.















