

FIELD REPORT

DATE: December 21, 2012
PROJECT: Independence Park Main Library
WEATHER CONDITIONS: Clear- 46°
SITE CONDITIONS: Dry
WORKERS: +/- 50
REPORTED BY: Benjamin R. Bradford, The Library Design Collaborative

IN ATTENDANCE: Benjamin R. Bradford

OBSERVATIONS:

- 1) The Monthly Owner's Meeting was held yesterday.
- 2) The cooling tower drilled shafts have been poured.
- 3) The loading dock drilled shafts have been poured.
- 4) Masonry has begun on the west end of the building.
- 5) The curtainwall is being installed.
- 6) The air barrier is being installed on the south side of the third floor.
- 7) The following work is being installed:
 - a. Exterior gypsum board sheathing
 - b. Metal studs
 - c. Air barrier
 - d. Fireproofing
 - e. Plumbing piping
 - f. Mechanical duct
 - g. Sprinkler system piping
 - h. Electrical conduits and junction boxes

CONSTRUCTION SCHEDULE:

- 1) Zinc wall panel installation is expected to start within the month.
- 2) The cistern concrete pad is expected to be poured within the month.

ATTACHMENTS:

- 1) Two (2) pages of photographs from the site visit.



