

Observation Report #1

Independence Park Library

SJB Personnel: Corey Blanchard
Contractor Personnel: Milton J. Womack
Inspection Date: 6/17/14 – 1:30 p.m.
Weather Conditions: Overcast, 87°
Site Condition: Dry

Visited site to observe construction progress and inspect for scheduled concrete pour. The scheduled pour is for the east portion of the parking lot. All form materials, reinforcement, and base appears to be in compliance with plans and specifications. The contractor mentioned a grading issue that was corrected along the north side of the northernmost parking isle. These areas were revisited with the project manager prior to the scheduled pour.

All erosion control devices were installed and in working order. Please do not hesitate to contact this office if you have any questions or concerns.

When asked, the contractor reported no problems.

Photos









X *Corey Blanchard*
Corey Blanchard, P.E.
Project Manager, SJB Group, LLC