## Observation Report #4 Independence Park Library

SJB Personnel:

Corey Blanchard Milton J. Womack

Contractor Personnel: Inspection Date:

8/7/14 - 2:30 p.m.

Weather Conditions:

Cloudy, 92°

**Site Condition:** 

Dry

Visited site to observe construction progress and inspect for scheduled concrete pour. The scheduled pour is for the main entrance drive in the center of the parking lot. All form materials, reinforcement, and base appears to be in compliance with plans and specifications. The contractor did not have geo fabric installed at time of inspection. Fabric is to be installed at all joints in the area where compaction could not be achieved. Contractor advised it would be completed prior to scheduled pour.

All erosion control devices were installed and in working order. Please do not hesitate to contact this office if you have any questions or concerns.

When asked, the contractor reported no problems.

## Photos





X long Blonchart

Corey Blanchard, P.E. Project Manager, SJB Group, LLC