

Observation Report #5

Independence Park Library

SJB Personnel: Corey Blanchard
Contractor Personnel: Milton J. Womack
Inspection Date: 8/28/14 – 1:45 p.m.
Weather Conditions: Partly Cloudy, 94°
Site Condition: Dry


Visited site to observe construction progress and inspect for scheduled concrete pour. The scheduled pour is for the area just west of the entrance and the southern aisle on the west parking lot. All form materials, reinforcement, and base currently installed appear to be in compliance with plans and specifications. Reinforcement for the drive aisle was not installed at the time of inspection, but workers were in the process of installing.

All erosion control devices were installed and in working order. Please do not hesitate to contact this office if you have any questions or concerns.

When asked, the contractor reported no problems.

Photos







X Corey Blanchard

Corey Blanchard, P.E.

Project Manager, SJB Group, LLC